

Sample Report

March 2006



Burdick Bros. Inc.
Quality Service Since 1985

VIBRATION ANALYSIS • LASER ALIGNMENT • DYNAMIC BALANCING

e-mail: bbi@abe.midco.net

Page 1 of 17

Attn:
Your Company
12345 678th Ave
Anytown, SD 57999

(605) 123-4567

March 30, 2006

INVOICE

No. 2301

PO #: -----

Vibration Data Collection:

Data Analysis/Reports
Mileage

\$ 382.50

4% Sales Tax \$ 15.30

Total ***\$ 397.80***

TERMS: Net 10th

THANK YOU!!

Next Scheduled Appointment: June 2006
Please let us know if this will not be suitable

COPY



VIBRATION ANALYSIS • LASER ALIGNMENT • DYNAMIC BALANCING

e-mail: bbi@abe.midco.net

Page 2 of 17

Table of Contents

3/8" COIL LINE DATA ANALYSIS REPORT SUMMARY	7
5341 Shear - Cincinnati	8
6684 Blast System.....	9
AERATION DATA ANALYSIS REPORT SUMMARY	12
AEB1 AERATION BLOWER #1	13
AEB2 AERATION BLOWER #2	14
PDB POSITIVE DISPLACEMENT BLOWER	15



Equipment Summaries

Equipment Not on This Summary is Appears to Be Operating Within Normal Working Tolerance

Or Was Not Operating at Time of Data Collection

3/8" Coil Line

6684 Blast System

- **Blast Cabinet Motor:** Elevated Vibration Levels at 1 x's rpm, Indicating Unbalance
- **Shot Blaster Motor #1:** Everything Appears to Be in Normal Working Order
- **Shot Blaster Motor #3:** High Vibration Levels with Harmonics of Running Speed, Indicating Unbalance and/or Looseness (See Graph)
- **Dynamically Balance or Check and/or Replace Blowers on Blast Cabinet and Shot Blast #3**

Aeration Blowers

AEB1 AERATION BLOWER #1

- **Vibration Levels are Within Normal Working Tolerance, But are Higher Than Aeration Blowers #2 and #3**

PDB POSITIVE DISPLACEMENT BLOWER

- **High Motor Vibration Levels at 1 x's Motor rpm, Usually Indicating Unbalance (See Graphs)**
- **Check for Eccentric Pulley**
- **Recheck Motor Vibration Levels with Belts Removed**



Summary

****Burdick Bros., Inc. Recommends reevaluating vibration levels on all equipment in approximately three months, to develop trends that accurately predict equipment problems.**

****All Bearing Numbers are needed to make a complete diagnosis**

****In order to develop accurate trends, we need to be informed of ALL repairs including: bearing, motor, shaft, etc. replacements that are done to the equipment. Bearing insert numbers are needed – housing numbers don't work with our software. Feel free to drop an e-mail to Deb at bbi@abe.midco.net or start a file of notes for Jim to pickup when he comes for the next visit. Include the machine name and/or number and where the bearing, shaft, etc. is located (Motor In, Motor Out, etc.), if applicable, so I can put replacement information with the proper machine and place.**

Note

****Bearing Condition Units (BCU) is an evaluation of the trend of shock impulses. No standards for evaluation limits are currently available, for this reason, trending is the best evaluation criterion.**

****Criteria for overall condition (Vibration Levels) rating (peak overall velocity, in/sec rms).**



3/8" Coil Line

3/8" COIL LINE DATA ANALYSIS REPORT SUMMARY.....	7
5341 Shear - Cincinnati	8
6684 Blast System.....	9



Your Company

5341 Shear – Cincinnati

**Everything Appears to Be in Normal Working Order

6684 Blast System

****Blast Cabinet Motor:** Elevated Vibration Levels at 1 x's rpm, Indicating Unbalance

****Shot Blaster Motor #1:** Everything Appears to Be in Normal Working Order

****Shot Blaster Motor #3:** High Vibration Levels with Harmonics of Running Speed, Indicating Unbalance and/or Looseness (See Graph)

****Dynamically Balance or Check and/or Replace Blowers on Blast Cabinet and Shot Blast #3**

****Periodic Monitoring**



5341 **Shear - Cincinnati**

	MOTOR	
<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
5341MIV	0.052	0.073
5341MIH	0.027	0.055
5341MIA	0.052	0.277
5341MOV	0.046	0.131
5341MOH	0.032	0.051

5341

Assessment:

****Vibration Levels are Within Normal Working Tolerance**

Action Recommended:

****Periodic Monitoring**



6684 Blast System

BLAST CABINET MOTOR

<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
6684BFMIV	0.162	0.069
6684BFMIH	0.105	0.098
6684BFMIA	0.299	0.135
6684BFMOV	0.253	0.069
6684BFMOH	0.219	0.098

SHOT BLASTER MOTOR #1

<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
6684SB1MIV	0.045	0.084
6684SB1MIH	0.048	0.168
6684SB1MIA	0.193	0.047
6684SB1MOV	0.093	0.175
6684SB1MOH	0.062	0.084

SHOT BLASTER MOTOR #3

<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
6684SB3MIV	0.269	0.190
6684SB3MIH	0.368	0.142
6684SB3MIA	0.800	0.222
6684SB3MOV	0.646	0.278
6684SB3MOH	0.270	0.789

6684

Assessment:

- **Blast Cabinet Motor: Elevated Vibration Levels at 1 x's rpm, Indicate Unbalance
- **Shot Blaster Motor #1: Vibration Levels are Within Normal Working Tolerance
- **Shot Blaster Motor #3: High Vibration Levels with Harmonics of Running Speed, Indicating Unbalance and/or Looseness (See 6684SB3MIH Spectrum Graph)


Action Recommended:

- **Dynamically Balance or Check and/or Replace Blowers on Blast Cabinet and Shot Blast #3
- **Periodic Monitoring



6684

Blast System



Aeration Blower

AERATION DATA ANALYSIS REPORT SUMMARY	12
AEB1 AERATION BLOWER #1	13
AEB2 AERATION BLOWER #2	14
PDB POSITIVE DISPLACEMENT BLOWER	15



Your Company

AEB1 AERATION BLOWER #1

**Vibration Levels are Within Normal Working Tolerance, But are Higher Than Aeration Blowers #2 and #3

AEB2 AERATION BLOWER #2

**Everything Appears to Be in Normal Working Order

PDB POSITIVE DISPLACEMENT BLOWER

**High Motor Vibration Levels at 1 x's Motor rpm, Usually Indicating Unbalance (See Graphs)

**Check for Eccentric Pulley

**Recheck Motor Vibration Levels with Belts Removed



Your Company

AEB1 AERATION BLOWER #1

<u>MOTOR</u>			<u>BLOWER</u>		
<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>	<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
AEB1MIV	0.033	0.352	AEB1BIV	0.045	0.254
AEB1MIH	0.134	0.268	AEB1BIH	0.214	0.243
AEB1MIA	0.041	0.145	AEB1BOV	0.075	0.377
AEB1MOV	0.095	0.152	AEB1BOH	0.114	0.297
AEB1MOH	0.197	0.131			

Assessment:

**Vibration Levels are in Within Normal Working Tolerance, But are Higher than Aeration Blower #2 and #3

Action Recommended:

**Periodic Monitoring



Your Company

AEB2 AERATION BLOWER #2

<u>MOTOR</u>			<u>BLOWER</u>		
<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>	<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
AEB2MIV	0.022	0.163	AEB2BIV	0.036	0.268
AEB2MIH	0.020	0.210	AEB2BIH	0.038	0.228
AEB2MIA	0.026	0.247	AEB2BOV	0.049	0.218
AEB2MOV	0.062	0.359	AEB2BOH	0.030	0.221
AEB2MOH	0.019	0.247			

Assessment:

**Vibration Levels are Within Normal Working Tolerance

Action Recommended:

**Periodic Monitoring



PDB POSITIVE DISPLACEMENT BLOWER

MOTOR

<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
PDBMIV	0.349	0.225
PDBMIH	0.222	0.087
PDBMIA	0.065	0.247
PDBMOV	0.508	0.276
PDBMOH	0.126	0.359
PDBMOA	0.231	0.149

SHAFT #1

<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
PDBBS1IV	0.174	0.858
PDBBS1IH	0.206	0.785
PDBBS1OV	0.160	0.742
PDBBS1OH	0.175	0.611

SHAFT #2

<u>Point Name</u>	<u>Vibration</u>	<u>BCU</u>
PDBBS2IV	0.199	0.447
PDBBS2IH	0.182	0.843
PDBBS2OV	0.190	0.713
PDBBS2OH	0.168	0.567

Assessment:


**High Motor Vibration Levels at 1 x's Motor rpm, Indicating Unbalance (See PDBMOV [1] Spectrum Graph and PDBMIV [1] Vibration Trend Graph)

Action Recommended:

- **Check for Eccentric Pulley
- **Recheck Motor Vibration Levels With Belts Removed
- **Periodic Monitoring



PDB POSITIVE DISPLACEMENT BLOWER



PDB

POSITIVE DISPLACEMENT BLOWER

